

## ABNORMAL TEST RESULT

OF MODEL LCA10S-51. Did Cheese Cloth or Paper Glow?

No.

2. Did Ground Fuse Open?

No.

3. Dielectric breakdown

No.

4. Other Results

See the following pages (1/6~6/6).

There was no emission of flame, molten metal, ignition of cheesecloth, dielectric breakdown, opening of the ground fuse, other indication of a shock or fire hazard.



ABNORMAL TEST RESULT

Component	Mode	Comment	Output Voltage (V)
C11	Short	F11 opened, No hazard.	0V
	Open	Normal operation.	
C12	Short	F11 opened, No hazard.	0V
	Open	Output voltage decreased. No hazard.	
C14	Short	F11 opened, No hazard.	0V
	Open	Output voltage decreased. No hazard.	
C15	Short	Normal operation.	
	Open	F11 opened, No hazard.	0V
C16	Short	Normal operation.	
	Open	Normal operation.	
C51	Short	Output voltage decreased. No hazard.	
	Open	Output voltage decreased. No hazard.	
C52	Short	No hazard.	0V
	Open	Normal operation.	
C53	Short	No hazard.	0V
	Open	Normal operation.	

ABNORMAL TEST RESULT

Component	Mode	Comment	Output Voltage (V)
C54	Short	No hazard.	0V
	Open	Normal operation.	
C59	Short	No hazard.	0V
	Open	Normal operation.	
C60	Short	Normal operation.	
	Open	Normal operation.	
C61	Short	Normal operation.	
	Open	Normal operation.	
D11	Short	Normal operation.	
	Open	No hazard.	0V
D12	Short	F11 opened.No hazard.	0V
	Open	Normal operation.	
D51	Short	Output voltage decreased. No hazard.	
	Open	No hazard.	0V
D52	Short	F11 opened.No hazard.	0V
	Open	No hazard.	0V
F11	Short	Normal operation.	
	Open	No hazard.	0V

ABNORMAL TEST RESULT

Component	Mode	Comment		Output Voltage (V)
IC51	Short	A-K R-K	Output voltage decreased. No hazard.	
		R-A	No hazard.	0V
	Open	A K R	No hazard.	0V
L11	Short	Normal operation.		
	Open	No hazard.		0V
L51	Short	Normal operation.		
	Open	No hazard.		0V
PC11	Short	LED	No hazard.	0V
		TR	No hazard.	0V
	Open	LED TR	No hazard.	0V
SS11	Short	F11 opened, No hazard.		0V
	Open	No hazard.		0V
T11 ⑤-①	Short	F11 opened. No hazard.		0V
	Open	No hazard.		0V
T11 ④-③	Short	F11 opened. No hazard.		0V
	Open	F11 opened. No hazard.		0V
T11 ⑥, ⑦ - ⑧, ⑨	Short	F11 opened. No hazard.		0V
	Open	F11 opened. No hazard.		0V



ABNORMAL TEST RESULT

Component	Mode		Comment	Output Voltage (V)
TR11	Short	C-E C-B	No hazard.	0V
		B-E	No hazard.	0V
	Open	C E B	No hazard.	0V
TR12	Short	C-E C-B	F11 opened. No hazard.	0V
		B-E	No hazard.	0V
	Open	C B E	No hazard.	0V
ZD11	Short		Output voltage decreased. No hazard.	
	Open		Output voltage decreased. No hazard.	
ZD51	Short		No hazard.	0V
	Open		Normal operation.	



ABNORMAL TEST RESULT

Component	Mode	Comment	Output Voltage (V)
R11	Open	Output voltage decreased. No hazard.	
R12	Open	Normal operation.	
R13	Open	Normal operation.	
R14	Open	Normal operation.	
R16	Open	F11 opened. No hazard.	0V
R17	Open	Normal operation.	
R51	Open	No hazard.	0V
R52	Open	Normal operation.	
R53	Open	No hazard.	0V
R54	Open	No hazard.	0V
R55	Open	Output voltage decreased. No hazard.	
R56	Open	Output voltage decreased. No hazard.	
R57	Open	Normal operation.	
R58	Open	Normal operation.	