

DATA SHEET		Date	June 6,2001
Model	MAX3200T	Temp.	25 °C
Test	Vibration/impact test 振動・衝撃試験	Humid.	45 %Rh
		Tested by	H.Morita

1. Conditions

- (1) Frequency : 10~150 Hz
(Vibration) 3 minutes period
周波数(振動)
- (2) Direction・Time : 60 minutes along X, Y and Z axis (Vibration)
方向・時間 11mS, once each X, Y and Z axis (Impact)

2. Conditions of Acceptability

- (1) No degradation of performance or loss of function after test.
試験後、諸機能が正常であること
- (2) No remarkably damage of appearance.
外観上著しい損傷がないこと
- (3) No looseness or a crack at solder joint.
はんだ付け、圧着など電氣的接合部分にクラックや緩みの発生がないこと

3. Result

(1) Vibration limit test

No.	Gravity [m/s ²]	Result	Note
1	29.4	OK	
2	-	-	
3	-	-	

All are satisfactory to item 3: OK

(2) Impact test

No.	Gravity [m/s ²]	Result	Note
1	294	OK	
2	-	-	
3	-	-	

All are satisfactory to item 3: OK